



CLAMP METER (MASS TECH MAKE)

SPECIFICATION

SPECIFICATION	
Display	3 1/2 digit LCD, with automatic polarity indication.
Terminal and earth ground	1000V DC or 750V rms AC (sine)
Measuring Method	Dual-slope integration A-D converter
Over range indication	" 1 " Figure only in the display
Polarity indication	displayed for negative polarity
Operating temperature	0°C to 40°C (32°F to 104°F)
Storage temperature	-10°C to 50°C (14°F to 122°F)
Power	9V alkaline or carbon-zinc battery(NEDA 1604)
Accessories	Operating manual, set of test leads
Low battery indication	" BAT " to left of display
Optional accessories	Thermocouple (K-type)
Dimension	90(W) x 230(D) x 43(H) mm
Weight	320g (including battery)
Resistance	2K Ω /20K Ω /200K Ω /2M Ω /20M Ω
Insulation Test	2000M Ω (Note>500 Ω)
AC Current	1000A